September 21, 1984

W3P84-2669 Q-3-A35.07.105 3-A1.01.04

Mr. J.T. Collins Regional Administrator, Region IV U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

REFERENCE: LP&L Letter W3K84-2035 dated August 30, 1984

SEP 2 7 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3

Docket No. 50-382

Significant Construction Deficiency No. 105

"Electrical Separation Deficiencies (Reg. Guide 1.75)"

The above referenced letter indicated submittal of the Final Report to the NRC on September 21, 1984.

At the present time, evaluation and minor rework is underway. Inspection Report 84-30, performed by the Construction Appraisal Team (CAT), indicated this item is closed. Final package assemblance and review is ongoing with a scheduled completion of mid October.

A final report is scheduled for transmittal to the NRC on October 19, 1984.

Very truly yours,

K.W. Cook

Nuclear Support & Licensing Manager

KWC/RJB/pbs

cc: Director

Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission

Washington, D.C. 20555

9410100680 840921 PDR ADDCK 05000382 PDR

IE-271/0

Mr. J.T. Collins W3P84-2669 Page 2

cc: Director
Office of Management
Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E.L. Blake Shaw, Pirtman, Potts & Trowbridge 1800 M. Street, N.W. Washington, D.C. 20236

Mr. W.M. Stevenson Monroe & Lemann 1424 Whitney Bldg. New Orleans, LA 70130

Mr. W.A. Cross 4827 Rugby Avenue Suite B-1 Bethesda, MD 20814