## U. S. NUCLEAR REGULATORY COMMISSION

## REGION III

Reports No. 50-266/84-08(DRSS); 50-301/84-06(DRSS)

Docket Nos. 50-266; 50-301 Licenses No. DPR-24; DPR-27 Safeguards Group IV

Licensee: Wisconsin Electric Power Company 231 W. Michigan Milwaukee, WI 53201

Facility Name: Point Beach Nuclear Plant, Units 1 and 2

Inspection At: Point Beach Site, Two Rivers, WI

Inspection Conducted: June 11-15, 1984

Date of Last Physical Protection Inspection: November 15-18 and 28, 1983

Type of Inspection: Unannounced Physical Protection Inspection

1) Haption Inspectors

Physical Protection Specialist

L. Belanger Physical Protection Specialist

Approved By:

R. Creed, Chief Physical Security Section

## Inspection Summary

Inspection on June 11-15, 1984 (Reports No. 50-266/84-08(DRSS); 50-301/84-06(DRSS)) Areas Inspected: Included a review of the Licensee's Action on Previous Inspection Findings; Security Plan and Implementing Procedures; Management Effectiveness -Security Program; Security Organization, Security Program Audit; Records and Reports; Testing and Maintenance; Security System Power Supply; Compensatory Measures; Access Control - Personnel Detection Aids - Protected and Vital Areas; Alarm Stations; Communications; and Independent Inspection. The inspection involved 64 inspector-hours by two NRC inspectors. Eight of the 64 inspector-hours were conducted offsite during offshift periods. The inspection began during the day shift.

> Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled

fuly 6, 1984 pate 7/6/84Date 7/6/84

8407160186 8407 PDR ADOCK 05000266

Results: The licensee was found to be in compliance with NRC requirements within the areas examined, except for the following item:

<u>Alarm Station</u>: A computer capability required by the security plan could be circumvented.

An area of concern was noted regarding written guidance by the security contractor pertaining to the reporting of possible violations to the NRC. Four commitments were made to resolve other concerns noted during the inspection. These concerns did not constitute violations of NRC requirements.

(Details - UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled