



Consumers
Power
Company

James W Cook
Vice President - Projects, Engineering
and Construction

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0453

June 29, 1984

82-16 #9

Mr J G Keppler, Regional Administrator
US Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER PROJECT
DOCKET NOS 50-329 AND 50-330
POTENTIAL 50.55(e) REPORT CONCERNING
PROCURED ELECTRICAL EQUIPMENT
FILE: 0.4.9.72 SERIAL: 30329

References: J W Cook letters to J G Keppler, same subject:

- 1) Serial 19130, dated December 30, 1982
- 2) Serial 20716, dated February 25, 1983
- 3) Serial 22197, dated May 13, 1983
- 4) Serial 22241, dated June 29, 1983
- 5) Serial 23769, dated August 12, 1983
- 6) Serial 23809, dated September 30, 1983
- 7) Serial 26644, dated December 23, 1983
- 8) Serial 28073, dated March 30, 1984

This letter, as were the referenced letters, is an interim report on a 10CFR50.55(e) condition concerning delivered, safety-related electrical equipment not meeting project requirements.

Site overinspection activity continues on those safety-related purchase orders for which equipment has been received at the jobsite. At this time, overinspection activity has been completed on thirty-four of the sixty-six purchase orders identified, with substantial completion on the remaining thirty-two purchase orders.

MPQAD continues to participate in final source inspection activities for six purchase orders where safety-related equipment still is being shipped.

The concerns on the use of the pull test is resolved and the pull test remains as the inspection technique to verify the tightness of crimped and screwed/bolted connections.

B407170386 840629
PDR ADOCK 05000329
S PDR


JUL 9 1984

OC0684-0028A-MP01

IE01
11

As a result of inspection activities associated with this 10CFR50.55(e) issue, a potentially reportable condition has just been detected and evaluation is still being conducted. The condition is as follows:
When the cover on the electrical termination compartment on ITT General, Model NH-91 and NH-95 valve operators is screwed on, it is damaging the insulation on a lead of a capacitor which is in the motor start circuit. This could result in shorting of the capacitor to the metal cover, inhibiting the function of the valve operator. Additional information on this condition will be provided in subsequent reports.

Another letter, either interim or final, will be sent on or before December 31, 1984.



JWC/AHB/cd

CC: Document Control Desk, NRC
Washington, DC

Midland NRC Resident Office
Midland Nuclear Plant

DSHood, USNRC Office of NRR

INPO Records Center

OM/OL SERVICE LIST

Mr Frank J Kelley
Attorney General of the
State of Michigan
Ms Carole Steinberg
Assistant Attorney General
Environmental Protection Division
720 Law Building
Lansing, MI 48913

Mr Myron M Cherry, Esq
Suite 3700
Three First National Plaza
Chicago, IL 60602

Mr Wendell H Marshall
RFD 10
Midland, MI 48640

Mr Charles Bechhoefer, Esq
Atomic Safety & Licensing
Board Panel
U S Nuclear Regulatory Commission
East-West Towers, Room E-413
Bethesda, MD 20014

Dr Frederick P Cowan
6152 N Verde Trail
Apt B-125
Boca Raton, FL 33433

Mr Fred C Williams
Isham, Lincoln & Beale
1120 Connecticut Ave, NW, Suite 840
Washington, DC 20036

Mr James E Brunner, Esq
Consumers Power Company
212 West Michigan Avenue
Jackson, MI 49201

Atomic Safety & Licensing
Appeal Board
U S Nuclear Regulatory Commission
Washington, DC 20555

Mr C R Stephens (3)
Chief, Docketing & Services
U S Nuclear Regulatory Commission
Office of the Secretary
Washington, DC 20555

Ms Mary Sinclair
5711 Summerset Street
Midland, MI 48640

Mr William D Paton, Esq
Counsel for the NRC Staff
U S Nuclear Regulatory Commission
Washington, DC 20555

Atomic Safety & Licensing
Board Panel
U S Nuclear Regulatory Commission
Washington, DC 20555

Ms Barbara Stamaris
5795 North River Road
Rt 3
Freeland, MI 48623

Dr Jerry Harbour
Atomic Safety & Licensing
Board Panel
U S Nuclear Regulatory Commission
East-West Towers, Room E-454
Bethesda, MD 20014

Mr M I Miller, Esq
Isham, Lincoln & Beale
Three First National Plaza
52nd Floor
Chicago, IL 60602

Mr D F Judd
Babcock & Wilcox
PO Box 1260
Lynchburg, VA 24505

Mr Steve Gadler, Esq
2120 Carter Avenue
St Paul, MN 55108

Mr P Robert Brown
Clark, Klein & Beaumont
1600 First Federal Bldg
Woodward Ave
Detroit, MI 48226

Mr John DeMeester, Esq
Dow Chemical Building
Michigan Division
Midland MI 48640

Ms Lynne Bernabei
Government Accountability Project
1901 Q Street, NW
Washington, DC 20009

3/14/84