

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power Corp.
Crystal River 3

Docket No. 50-302
License No. DPR-72

The following violation was identified during an inspection conducted on February 27 - March 2, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1 requires that written procedures be established, implemented and maintained covering the applicable procedures recommended in Appendix "A" of Regulatory Guide 1.33. Regulatory Guide 1.33, Appendix "A" states in part that procedures will be reviewed and approved.

Contrary to the above, Emergency Plan Implementing Procedure EM-307 which was reviewed on December 19, 1983, and approved December 30, 1983 conflicted with Operating Procedure OP-301, in that certain valve alignments required by both procedures were contradictory. This resulted in the Post Accident Sampling System being inoperable with regards to returning a sample to containment in accordance with the procedure. This is a failure to perform an adequate review of procedures.

This is a Severity Level IV violation (Supplement IV).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: APR 30 1984