

ENCLOSURE 1

NOTICE OF VIOLATION

Duke Power Company  
Catawba

Docket Nos. 50-413 and 50-414  
License Nos. CPPR-116 and CPPR-117

The following violation was identified during an inspection conducted on May 1-4, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criteria V as implemented by QA Topical Report (Duke-1A) Section 17.1.5.2 requires that activities affecting quality be accomplished in accordance with prescribed instructions, procedures, or drawings. Procedure M-2, Revision 8, Inspection of Design Concrete, specifies that honeycomb shall be identified after concrete forms are removed.

Contrary to the above, discussions with responsible engineers and examination of documentation showed that numerous honeycomb defects were not identified at the time of form removal in concrete pours made prior to 1979.

This is a Severity Level IV violation (Supplement II).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date:     MAY 24 1984    

8407180163 840706  
PDR ADOCK 05000413  
Q PDR