




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET • P.O. BOX 8008
NEW ORLEANS, LOUISIANA 70174-8008 • (504) 366-2345

September 24, 1984

W3P84-2697
Q-3-A35.07.114
3-A1.01.04

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 114
"DAMAGED SAFETY RELATED SYSTEMS
DUE TO WATERHAMMERS"
Fourth Interim Report

REFERENCE: LP&L letter W3P84-2552 dated September 14, 1984

The above referenced letter indicated submittal of the final report to the NRC on September 21, 1984.

At the present time, corrective action is considered complete however, corrective action verification is ongoing. The final report is scheduled to be submitted to the NRC on October 19, 1984.

Very truly yours,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/RJB/ss

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8410150465 840924
PDR ADOCK 05000382
S PDR

1/0 22-27

Mr. John T. Collins
W3P84-2697
Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W. A. Cross
4827 Rugby Avenue
Suite B-1
Bethesda, Maryland 20814