ATTACHMENT I OPERATING DATA REPORT

OPES	RATING STATUS		ВУ	FORT CAL OCTOBER D. L. L.	
	Unit Name: FORT CALHOUN STATION Reporting Period: AUGUST 1995			NOTES	
4. 5. 6.	Licensed Thermal Power (MWt): 1500 Nameplate Rating (Gross MWe): 502 Design Elec. Rating (Net MWe): 478 Max. Dep. Capacity (Gross MWe): 502 Max. Dep. Capacity (Net MWe): 478				
	If changes occur in Capacity Ratings give reasons: N/A	(3 through 7) si	nce last	report,
9.	Power Lavel to which restricted, if a	any (Net MWe)	: N/	A	
10.	Reasons for restrictions, if any: N/A				
		THIS MONTH			CUMULATIVE
18. 19. 20. 21. 22. 23.	Hours in Reporting Period Number of Hours Reactor was Critical Reactor Reserve Shutdown Hours Hours Generator On-line Unit Reserve Shutdown Hours Gross Thermal Energy Generated (MWH) Gross Elec. Energy Generated (MWH) Net Elec. Energy Generated (MWH) Unit Service Factor Unit Availability Factor Unit Capacity Factor (using MDC Net) Unit Capacity Factor (using DER Net) Unit Forced Outage Rate Shutdowns scheduled over next 6 month N/A	304623.0 93.0 93.0 85.7 85.7	61 20 19	5831.0 4361.1 .0 4277.2 .0 54493.1 45918.0 48616.0 73.4 73.4 69.9 69.9 6.1	192265.0 150779.0 1309.5 149051.5 .0 198303193.6 65450800.2 62440408.3 77.5 77.5 70.2 68.6 4.1
	If shut down at end of report period,				
26.	Units in test status (prior to comm. INITIAL CRITICALITY INITIAL ELECTRICITY COMMERCIAL OPERATION	oper.): N/A	For	ecast	Achieved

9510190233 951013 PDR ADDCK 05000285 R PDR

ATTACHMENT III UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-285

UNIT NAME Fort Calhoun St.

DATE October 6, 1995

COMPLETED BY D. L. Lippy

TELEPHONE (402) 533-6843

REPORT MONTH August 1995

No.	Date	Type ¹	Duration (Hours)	Reason	Method of Shutting Down Reactor ²	Licensee Event Report No.	System Code ⁴	Component Code ^s	Cause & Corrective Action to Prevent Recurrence
95-04	950824	F	52.4	н	3	95-005	ZZ	ZZZZZZ	At 1114 hours on August 24, 1995 the plant experienced a reactor trip and associated diesel generator (DG) start. The trip occurred during the performance of the Diverse Scram System Actuation Relay Operability Test, when a licensed operator inadvertently repositioned the incorrect switch from TEST to NORMAL. All systems responded normally to the trip with the exception of DG-1 going to full speed vice idle speed. Corrective action includes institutionalizing the use of peer checking for switch manipulations that could immediately cause a reactor trip. The reactor was taken critical at 0220 hours on August 26th.

F: Forced

Reason:

S: Scheduled A-Equirent Failure (Explain)

B-Maintenance or Test

C-Refueling

D-Regulatory Restriction

E-Operator Training & License Examination

F-Administrative H-Other (Explain) Method:

1-Manual

2-Manual Scram

3-Automatic Scram

4-Other (Explain)

4

Exhibit F - Instructions for Preparation of Data Entry Sheets for Licensee

Event Report (LER) File (NUREG-0161)

5

Exhibit H - Same Source