

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

34 JUL 3, 1984 12


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Re: Catawba Nuclear Station  
Units 1 and 2  
Docket Nos. 50-413 and 50-414  
Significant Deficiency No. 413-414/83-17  
Special Weld Boss Restrictor Applications

Dear Mr. O'Reilly:

My letter of March 29, 1984 stated that all corrective action for Unit 2 concerning the subject deficiency would be complete by June 30, 1984. In our investigation, we found 8 locations of the 70 restrictor locations, to be overdrilled, 2 applications that require further evaluation and 2 that are not yet installed. Due to the required rework for these situations, additional time is needed to clear this deficiency. This work should be completed by August 24, 1984.

Very truly yours,



Hal B. Tucker

LTP/rhs

Attachment

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector  
Catawba Nuclear Station

Palmetto Alliance  
2135½ Devine Street  
Columbia, South Carolina 29205

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

Mr. Robert Guild, Esq.  
Attorney-at-Law  
P. O. Box 12097  
Charleston, South Carolina 29412

Mr. Jesse L. Riley  
Carolina Environmental Study Group  
854 Henley Place  
Charlotte, North Carolina 28207

8407250356 840703  
PDR ADOCK 05000413  
S PDR

ORIGINAL COPY

IE 27/10