
DMB



July 24, 1984

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Richard P. Crouse Vice President Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the routine safeguards inspection conducted by Messrs. B. W. Stapleton and G. L. Pirtle of this office on June 25-29, 1984, of activities at the Davis-Besse Nuclear Power Station, Unit One, authorized by NRC Operating License No. NPF-3, and to the discussion of our findings with Mr. G. Grime and other members of the Toledo Edison Company at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as specified in the enclosed Appendix. A written response is required. Additionally, a concern has developed regarding your computer system. This concern is addressed in Paragraph 10 of the Report Details. We request that you advise us in writing, within 30 days of the receipt of this letter, of actions taken to resolve this concern.

Commitments made to resolve concerns noted during the inspection are described in Paragraph 3 of the Report Details. Please advise us if our understanding of your proposed actions is incorrect.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Section 73.21(c)(2) of the NRC's "Rules of Practice," Part 73, Title 10, Code of Federal Regulations. This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, the enclosure to this letter, our report of this inspection, and your response to the noncompliance identified in the enclosure to this letter will not be placed in the Public Document Room. Therefore, your statement of corrective action regarding the noncompliance identified in the enclosure should be submitted as a separate enclosure to your transmittal letter in the manner prescribed.

FOUNDO

8407310097 840724 PDR ADOCK 05000346 G PDR Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled

INEO

DMB TEOH

Toledo Edison Company

.

The responses directed by this letter and the accompanying Notice (Order) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Nuclear Materials Safety and Safeguards Branch


Enclosures: 1. Appendix, Notice of Violation 2. Inspection Report

No. 50-346/84-13(DRSS) (UNCLASSIFIED SAFEGUARDS INFORMATION)

cc w/encls: T. D. Murray, Station Superintendent IE File IE/DQASIP/ORPB IE/ES NMSS/SGPL NRR/DL/SSPB ACRS

cc w/encls, w/o UNCLASSIFIED SAFEGUARDS INFORMATION: DMB/Document Control Desk (RIDS) Resident Inspector, RIII Harold W. Kohn, Ohio EPA James W. Harris, State of Ohio Robert H. Quillin, Ohio Department of Health

RIII RIII Sup Stapleton/bl Pirtle 07/23/84





2