



DMB



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

June 15, 1984

Mr. J. G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
US Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Prairie Island Nuclear Generating Plants
Docket No. 50-282, License No. DR-42 and
Docket No. 50-306, License No. DRP-60

In our February 3, 1984 response concerning Inspection Reports No. 50-282/83-19 (DPRP) and 50-306/83-20 (DPRP), we committed to implementation of the revised plant modification system by July 1, 1984. Administrative procedures for the revised system have been finalized and training is in progress. We feel, though, that implementation at July 1 would unnecessarily complicate work to be done at the upcoming Unit 2 outage. For this reason, we will delay implementation of the revised plant modification system to August 1, 1984.

C. E. Larson
Vice-President
Nuclear Generation

cc: J. Hard
G. Charnoff

8407310165 840615
PDR ADOCK 05000262
G PDR

TES061384RLA02

JUN 21 1984

IEO/110