

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power and Light Company
Turkey Point

Docket No. 50-251
License No. DPR-41

The following violation was identified during an inspection conducted on May 1-4, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification sections 4.14.1 and 4.14.2 require visual inspection of mechanical snubbers to insure there are no visible indications of impaired operability and that attachments to the supporting structure are secure.

Contrary to the above, the licensee failed to perform a visual inspection of the Unit 4 mechanical snubbers prior to removal of the snubbers for functional testing.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JUN 4 1984

8407310239 840713
PDR ADOCK 05000251
Q PDR