COOPER NUCLEAR STATION
P.O. BOX 98, BROWNVILLE, NEBRASKA 68321
TELEPHONE (402)825-9811
FAX (402)825-5211

NLS950157 October 18, 1995

U.S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, D.C. 20555

Subjec

Third Ten-Year Interval Inservice Inspection Program Cooper Nuclear Station Docket No. 50-298, License No. DPR-46


Reference:

- Letter (No. NLS950036) to U.S. NRC Document Control Desk from Nebraska Public Power District dated January 26, 1995, "Transmittal of Cooper Nuclear Station License Event Report No. 94-032"
- Letter (No.NLS950144) to U.S. NRC Document Control Desk from Nebraska Public Power District dated July 21, 1995, "Third Ten-Year Interval Inservice Inspection Relief Request"
- 3) Letter to G. R. Horn (NPPD) from James R. Hall (NRC NRR) dated September 20, 1995, "Withdrawal of Request for Relief from the Requirements of 10 CFR 50.55a; High Pressure Coolant Injection (HPCI) Turbine Exhaust Line Pressure Boundary," (TAC No. M93037)

Gentlemen:

Enclosed is the initial revision of the Cooper Nuclear Station's (CNS's)Third Ten-Year Interval Inservice Inspection (ISI) program. This program is being submitted for Nuclear Regulatory Commission (NRC) review and approval per the requirements of 10 CFR 50.55a and has been prepared as part of the corrective actions and commitments stated in Reference 1. Please note that in Reference 2, the Nebraska Public Power District (District) submitted Relief Request RI-01 to allow for the presence of a fillet weld on the 10-inch diameter branch connection to the High Pressure Coolant Injection (HPCI) turbine exhaust line at CNS. This relief request has been subsequently withdrawn, as documented in Reference 3 and noted in the enclosed submittal.

240107





U.S. Nuclear Regulatory Commission October 18, 1995 Page 2 of 2

NRC approval of the relief requests contained in the enclosed submittal is requested by December 31, 1995. The Third Ten-Year interval is scheduled to begin on January 1, 1996, pending completion of the Fall 1995 refueling outage. If you have any questions, or need any additional information, please contact me.

Sincerely,

J. H. Mueller Site Manager

/dnm Enclosure

cc: Regional Administrator USNRC Region IV Arlington, TX

> NRC Resident Inspector Cooper Nuclear Station

NRC NRR Project Manager Rockville, MD

NPG Distribution

Correspondence No: NLS950157

The following table identifies those actions committed to by the District in this document. Any other actions discussed in the submittal represent intended or planned actions by the District. They are described to the NRC for the NRC's information and are not regulatory commitments. Please notify the Licensing Manager at Cooper Nuclear Station of any questions regarding this document or any associated regulatory commitments.

COMMITMENT	COMMITTED DATE OR OUTAGE
There are no new commitments contained in this correspondence.	N/A
A THIRD STREET AND A STREET STREET	
C. Statistica C. C. C. C. C. C. C. State B.C.	