



**GPU Nuclear Corporation**  
Post Office Box 388  
Route 9 South  
Forked River, New Jersey 08731-0388  
609 971-4000  
Writer's Direct Dial Number:

July 26, 1984

Mr. Dennis M. Crutchfield, Chief  
Operating Reactors Branch No. 5  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555


Dear Mr. Crutchfield:

Subject: Oyster Creek Nuclear Generating Station  
Docket No. 50-219  
IE Bulletin No. 80-11  
Revaluation of Safety-Related Masonry Walls

The attached Topical Report represents our reevaluation of the design adequacy of all but four identified masonry walls. The four walls which require further analysis are located in the Reactor Building southeast stairwell and will be modified during the next (Cycle 11) refueling outage. Results of the analysis will be forwarded to you by March 1985. The attachment revises our previous report which was provided by letter dated April 30, 1981.

If additional information or further clarification is needed, please contact Paul Czaya at (609)971-4893.

Very truly yours,

  
Peter B. Fiedler  
Vice President and Director  
Oyster Creek

PBF/dam  
Attachment

cc: Dr. Thomas E. Murley, Administrator  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

NRC Resident Inspector  
Oyster Creek Nuclear Generating Station  
Forked River, NJ 08731

8407310374 840726  
PDR AD0CK 05000219  
Q PDR

IE 11  
1/1