



PSEG Public Service
Electric and Gas
Company

80 Park Plaza, Newark, NJ 07101 / 201 430-8217 MAILING ADDRESS / P.O. Box 570, Newark, NJ 07101

Robert L. Mittl General Manager
Nuclear Assurance and Regulation

October 18, 1984

Director of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
7920 Norfolk Avenue
Bethesda, MD 20814

Attention: Mr. Albert Schwencer, Chief
Licensing Branch 2
Division of Licensing

Gentlemen:

HOPE CREEK GENERATING STATION
DOCKET NO. 50-354
DRAFT SAFETY EVALUATION REPORT
FSAR QUESTION 430.81

Attached is a copy of revised FSAR Question 430.81 previously transmitted on September 28, 1984.

Should you have any questions or require any additional information on these items, please contact us.

Very truly yours,

R. L. Mittl / RDM

Attachment

C D. H. Wagner
USNRC Licensing Project Manager (w/attach.)

W. H. Bateman
USNRC Senior Resident Inspector (w/attach.)

8410220130 841018
PDR ADDCK 05000354
PDR

The Energy People

*15001
1/1*

ATTACHMENT

HCGS FSAR

QUESTION 430.81 (SECTION 9.5.4)

In Section 9.5.4.2.1 of the FSAR you state that "The interior and exterior surfaces of the [fuel oil storage] tank are corrosion protected by carboline carbo zinc 11 coatings. I&E circular 77-15 discusses the incompatibility between diesel fuel oil and zinc. The reaction results in a substance resembling soap which when heated becomes insoluble and this substance could render diesel generators inoperable due to blocked fuel lines, injectors, etc. This is not acceptable. It is our position that fuel oil storage tanks be provided with internal corrosion protection. Therefore provide the results of tests which show that over the lifetime of the plant that the carboline carbo zinc 11 coating used is compatible with the type of diesel fuel oil that will be used at your plant and that the condition described in the circular will not occur or replace the internal coating with a non-zinc base type that is compatible with diesel fuel oil. (SRP 9.5.4, Part II)

RESPONSE

Hope Creek will remove the existing inorganic zinc coating from the diesel generator fuel oil tanks. The tanks will be blasted to the white metal criteria of SSPC-SP5. Two coats of Amercoat No. 90 or equivalent will be applied to the tank interior,