

ML261

November 15, 1982

MEMORANDUM FOR: D. Okrent, Chairman, ACRS Subcommittee on Midland Plant
 FROM: D. Fischer, Staff Engineer
 SUBJECT: MIDLAND PLANT QUALITY ASSURANCE

Attached for your information and use is an interim 50.55(e) report concerning quality assurance program and manufacturing deficiencies at Midland. These deficiencies affect radiation monitoring equipment being supplied by Victoreen, Inc. of Cleveland, Ohio. I would like to point out to you that the Management Corrective Action Report does not identify the Midland Plant Quality Assurance Department (MPQAD) as having detected defective workmanship in the Victoreen equipment delivered to the site. None of the corrective actions proposed by Consumers are directed at Consumers' receipt inspection program.

Since quality assurance will be one of the topics to be discussed at the next Midland Plant Subcommittee meeting, you may want to include a discussion of Consumers' receipt inspection program.

Attachment:
 As stated

cc: ACRS Members
 ACRS Technical Staff
 Midland Subcommittee Consultants

FILE: Midland
 B 249529 (Attachment)

B408010160 B40718
 PDR FOIA
 RICE84-96 PDR

OFFICE	D FISCHER:jk						
SURNAME	11/15/82						
DATE							