

LOUISIANA

POWER & LIGHT/Waterford 3 SES/P.O.Box B/Killona, LA 70066

July 19, 1984


W3K84-1657
Q-3-A35.07.105

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L Letter W3K84-1504 dated June 29, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 105
"Electrical Separation Deficiencies (Regulatory Guide 1.75)"
Second Interim Report



The above referenced letter indicated submittal of the Final Report to the USNRC on July 20, 1984.

At the present time, additional walkdowns, engineering evaluations, and corrective action is scheduled to be completed in early August 1984.

An Interim and/or Final Report will be submitted to the USNRC on August 17, 1984.

Very truly yours,

T. F. Gerrets
Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

840801039⁹ 840719
PDR ADOCK 05000382
S PDR

LE-27 /0

Mr. John T. Collins

July 19, 1984

W3X84-1657

Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814