

POST OFFICE BOX 2951 + BEAUMONT, TEXAS 77704


AREA CODE 713 838-6631

October 18, 1984 RBG-19193 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-168



An interim or final status report concerning the interpretation of W3 Welding Procedure used in performing rework and/or repair welding of non-low-carbon grades of austenitic stainless steel pipe will be provided by December 6, 1984.

Sincerely,

J. E. Booker

Manager-Engineering,

Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PJD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8411050315 841018 PDR ADOCK 05000458 PDR

IE-2710