Docket No. 50-346

Toledo Edison Company ATTN: Mr. W. Johnson President Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the meeting which R. C. DeYoung, C. Norelius, and myself held with you and R. Crouse on October 2, 1984. This meeting was held to discuss regulatory improvements at the Davis Besse facility.

Based on our review of the regulatory performance of the Davis Besse facility over the past few years, the results of the recent PAT inspection, the timeliness of actions to improve the training program, and recent operating events that have occurred at the facility, we expressed concern that activities undertaken to improve regulatory performance at the facility are not progressing at a rate necessary to ensure the level of excellence desired at the Davis Besse facility. We recognize that the company has been involved in a performance enhancement program and has taken steps to improve its regulatory performance. However, the items identified above indicate that such action has not been timely nor effective in all areas. During the meeting you indicated your desire to achieve a high level of excellence for operations of the Davis Besse facility.

We continue to be concerned that corrective actions may not be progressing at an appropriate rate to achieve improved operations in a timely manner. We plan to work with your staff to obtain commitment dates for carrying out the action items developed as a part of the performance enhancement program.

Sincerely,

Original signed by A. Bert Davis

James G. Keppler Regional Administrator

cc: T. D. Murray, Station
Superintendent
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert H. Quillin, Ohio
Department of Health
R. C. DeYoung, IE

Jackiw/1s 10/30/84 RIII Shaffer 10/ /84 Noret 1430 10/30/84

RIII Davis 10/1/84 Keppler 10///84