Southern California Edison Company



SAN ONOFRE NUCLEAR GENERATING STATION
P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

J. G. HAYNES

TELEPHONE (714) 492-7700

July 25, 1984

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Docket No. 50-361 and 50-362

30-Day Report

Licensee Event Report No. 84-041

San Onofre Nuclear Generating Station, Units 2 and 3

References: (1) Letter, J. G. Haynes (SCE) to J. B. Martin (NRC), dated April 25, 1984, Licensee Event Report 84-024

> (2) Letter, K. P. Baskin (SCE) to H. R. Denton (NRC), dated March 19, 1984, "FHA Update Consistent with 10 CFR 50.71(e)"

Pursuant to 10 CFR 50.73 and License Condition 2.G to Facility Operating Licenses NPF-10 and NPF-15 for Units 2 and 3, respectively, this submittal provides the 24-hour telephone report, 14-day Follow-up Report, and Licensee Event Report (LER) Number 84-041 (Docket No. 50-361) for apparent Fire Protection Program discrepancies. Since these occurrences involved shared systems between Units 2 and 3, a single LER for Unit 2 is enclosed in accordance with NUREG-1022.

As indicated in Reference 1, discrepancies have been discovered during our continuing review (see LER 84-001, Docket No. 50-361) associated with the updated Fire Hazards Analysis (FHA) (Reference 2). Two NCR's, additional examples of deficiencies reported previously in Reference 1, have been identified. Corrective actions, described in Reference 1, will be implemented.

The health and safety of plant personnel and the public were not affected by these discrepancies.



If you require any additional information, please so advise.

Vor Haynes

Enclosure: LER No. 84-041

cc: A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3) J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

J. B. Martin (Regional Administrator, NRC Region V)

Institute of Nuclear Power Operations (INPO)