PHILADELPHIA ELECTRIC COMPANY 2301 MARKET STREET P.O. BOX 8699 PHILADELPHIA, PA. 19101 (215) 841-5001 SHIELDS L. DALTROFF VICE PRESIDENT August 3, 1984 Docket No. 50-278 Mr. Darrell G. Eisenhut, Director Division of Licensing U.S. Nuclear Regulatory Commission Washington, D.C. 20555 Supplement II to Repair to the PBAPS Unit 3 SUBJECT: Jet Pump Instrumentation Penetrations 1) Letter to D. G. Eisenhut from REFERENCE: S. L. Daltroff dated June 20, 1984 (Repair to the Jet Pump Instrumentation Penetrations) Letter to D. G. Eisenhut from S. L. Daltroff dated July 23, 1984 (Supplement to Repair to the Jet Pump Instrumentation Penetrations) Dear Mr. Eisenhut: This supplement to our above referenced submittal letters of June 20, 1984 and July 23, 1984, S. L. Daltroff (PECo) to Dr. T. E. Murley (NRC), provides the results of the Residual Stress Analysis of the Peach Bottom Atomic Power Station Unit 3 Reactor Pressure Vessel Jet Pump Instrument Nozzle Seal Weld Overlays. The enclosed Attachment A, General Electric Company document MAR 84-27, Revision 1, "Residual Stress Analysis of the Peach Bottom Unit 3 Jet Pump Instrumentation Nozzle Weld Overlay", describes the results of the residual stress analysis of the weld overlay, including the effects of the instrument tube NOTE: PROP CY TO REG. FILE ONLY ADD spacer disk. 8408070303 840803

PLEASE NOTE THAT THE INFORMATION CONTAINED IN ATTACHMENT A HAS BEEN HANDLED AND CLASSIFIED AS PROPRIETARY BY THE GENERAL ELECTRIC COMPANY, as indicated in Attachment B, "General Electric Company Proprietary Affidavit", and we request that the information contained in Attachment A be withheld from public disclosure in accordance with the provisions of 10 CFR 2.790.

The delay of this information submittal has been discussed with the NRC's Peach Bottom Atomic Power Station Project Manager. In order to expedite its availability to the NRC staff, a separate information package will be dispatched directly to them through the project manager.

Submission of this attached report completes the information related to the repair of the Peach Bottom Atomic Power Station Unit 3 Reactor Pressure Vessel Jet Pump Instrument Nozzle Seals N8-A and N8-B as requested by the NRC staff at Bethesda, Maryland, during a June 18, 1984 meeting.

Should you have any questions or require additional information, please do not hesitate to contact us.

Very truly yours,

Malty

Attachments

cc: Dr. T. E. Murley, Administrator Mr. A. R. Blough, Site Inspector