

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

August 2, 1984

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Ms. E. G. Adensam, Chief
Licensing Branch No. 4


Re: Catawba Nuclear Station
Docket Nos. 50-413 and 50-414

Dear Mr. Denton:

During the NRC Staff's 10 CFR 50 Appendix R review of Catawba, a concern was expressed relative to the false opening of the main steam isolation valves or the steam generator power operated relief valves for steam generators "A", "B", and "D", due to a possible combination of fire induced spurious shorts in the control circuitry for the respective solenoid operators.

In order to resolve this concern, a modification will be implemented on Unit 1 prior to entry into Mode 3 which provides disconnect capability for the cables providing power to these solenoids. The disconnect will also provide a means to short across the solenoid coils, thus, providing additional depth of protection. This method of assuring the isolation of steam generators "A", "B", and "D" is identical to the method utilized on steam generator "C".

Very truly yours,



Hal B. Tucker

B002
1/1

ROS/slb

cc: Mr. James P. O' Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Palmetto Alliance
2135½ Devine Street
Columbia, South Carolina 29205

NRC Resident Inspector
Catawba Nuclear Station

Mr. Jesse L. Riley
Carolina Environmental Study Group
854 Henley Place
Charlotte, North Carolina 28207

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

8408070322 840802
PDR ADOCK 05000413
F PDR