

846  
RELATED CORRESPONDENCE

LAW OFFICES OF

**BISHOP, LIBERMAN, COOK, PURCELL & REYNOLDS**

1200 SEVENTEENTH STREET, N. W.  
WASHINGTON, D. C. 20036  
(202) 857-9800  
TELEX 440574 INTLAW U

DOCKETED  
USNRC

IN NEW YORK

BISHOP, LIBERMAN & COOK  
26 BROADWAY  
NEW YORK, NEW YORK 10004  
(212) 248-6900  
TELEX 222767

'84 AGO -8 119:08

OFFICE OF SECRETARY  
DOCKETING & SERVICE  
BRANCH

August 7, 1984

Peter B. Bloch, Esquire  
Atomic Safety and Licensing Board  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dr. Walter H. Jordan  
881 West Outer Drive  
Oak Ridge, Tennessee 37830


Dr. Kenneth A. McCollom, Dean  
Division of Engineering,  
Architecture & Technology  
Oklahoma State University  
Stillwater, Oklahoma 74078

Subj: Texas Utilities Electric Company, et al.  
(Comanche Peak Steam Electric Station,  
Units 1 and 2; Docket Nos. 50-445 and 50-446) OL

Gentlemen:

Attached hereto is a correction sheet reflecting several minor corrections in "Affidavit of John C. Finneran, Jr., Robert C. Iotti and R. Peter Deubler Regarding Design of Richmond Inserts and Their Application to Support Design" attached to "Applicants' Motion for Summary Disposition of CASE's Allegations Regarding Richmond Inserts" filed in this proceeding on June 2, 1984.

Sincerely,



William A. Horin  
Counsel for Applicants

rcm  
Attachment

cc: Board and Parties - Overnight Delivery  
Remainder of Service List - First Class Mail

8408080413 840807  
PDR ADOCK 05000445  
G PDR

DS03

ATTACHMENT

Corrections to  
"Affidavit of John C. Finneran, Jr., Robert C. Iotti and  
R. Peter Deubler Regarding Design of Richmond Inserts  
and Their Application to Support Design"

---

1. Page 20, line 18: " $d_2$ " and " $d_2$ " in this line should be reversed.
2. Page 38, Table G: For 4x4x1/4 Tube Steel the figure "42.16" should be "56.22."
3. Page 38: In the second line below Table G the words "at least" should be changed to "about."
4. Page 5, Attachment D: In figure D-1 "b" should be "b/2."