



Commonwealth Edison
1400 Opus Place
Downers Grove, Illinois 60515

March 13, 1992

Dr. Thomas E. Murley, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Attn. Document Control Desk

Subject: Byron Station Units 1 and 2
Regulatory Guide 1.97 Compliance
Tac Nos. M57198 and M63250
NRC Docket Nos. 50-454 and 50-455

Reference:(a) May 23, 1991 letter from A. Checra
to Dr. T.E. Murley

Dear Dr. Murley:

The purpose of this letter is to provide the NRC Staff notification of completion of an activity, to which a commitment was made in prior correspondence. The replacement of the RHR heat exchanger outlet temperature instrumentation with environmentally qualified instrumentation was completed on Byron Unit 1 during the Fall 1991 refueling outage. With completion of this modification, all commitments made for Byron Units 1 and 2 compliance with Regulatory Guide 1.97 are completed. The letter of Reference (a) indicated all other Byron Unit 1 and 2 commitments were completed.

Please direct any questions you may have concerning these matters to this office.

Respectfully,

Terence K. Schuster
Nuclear Licensing Administrator

cc: A.H. Hsia - Project Manager, NRR
W. Kropp - Senior Resident Inspector, Byron
A. Bert Davis - Regional Administrator - RIII

9203200245 920313
PDR ADOCK 05000454
P PDR

ZNLD/867/39

A003
1/0