



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
700 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

OCT 1 1981

MEMORANDUM FOR: D. Boyd, Project Leader, Midland SALP Report

FROM: G. Pirtle, SALP Coordinator, Division of Engineering  
and Technical Inspection

SUBJECT: SUPPLEMENTAL SALP INPUT FOR MIDLAND

After management review, the DETI SALP input for Midland, sent to you on September 22, 1981, is changed as follows:

- a. Page 1, Quality Assurance functional area, (Electrical and Instrumentation Input):
  1. Delete Section B which reads "Rating: Average."
  2. Delete Section C which reads "Comments: Recommend increased inspection effort ..."
- b. Page 2, Quality Assurance functional area, (Civil Engineering Input):
  1. Add on Page 2, Section B "Rating" after the last sentence: "Conversely, the Quality Assurance program as it pertains to the electrical and instrumentation area appeared satisfactory."
  2. Add on Page 2, Section C "Comments" after "... March 1981 management meeting." to read, "... March 1981 management meeting and to confirm the effectiveness of corrective actions already initiated."

The above changes are required to provide an "overall" DETI rating for the Quality Assurance functional area (Below Average) and consolidate comments for the recommended increased inspection frequency.

The project engineer for the Midland SALP report has been advised of the overall rating for the Quality Assurance functional area.

*Gary S. Pirtle*  
G. Pirtle, SALP Coordinator  
Division of Engineering and  
Technical Inspection

8408150747 840718  
PDR FOIA  
RICE84-96 PDR

cc: C. E. Norelius