DUKE POWER COMPANY P.O. BOX 33189 CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
SUCLEAR PRODUCTION

July 25, 1984 | 18

TELEPHONE (704) 373-4531

Mr. James P. O'Reilly, Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

Re: Catawba Nuclear Station Units 1 and 2 Docket Nos. 50-413 and 50-414 SD 413-414/81-11

Dear Mr. O'Reilly:

My letter of June 13, 1984 stated that all corrective action for this deficiency would be complete for Unit 2 by August 15, 1984. There are nine remaining valves that require testing to assure that they were properly modified by Borg Warner. This entails stroking the valve with the EMO several times.

Several of these valves cannot be tested because the EMO's have been temporarily removed for modification. Testing will be completed as these EMO's are made available. All corrective action for Unit 2 will, therefore, be completed by October 1, 1984.

Very truly yours,

H.B. Tucher 1861

Hal B. Tucker

LTP/rhs

cc: Director
 Office of Inspection & Enforcement
 U. S. Nuclear Regulatory Commission
 Washington, D. C. 20555

NRC Resident Inspector Catawba Nuclear Station

Palmetto Alliance 2135½ Devine Street Columbia, South Carolina 29205 INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

Mr. Robert Guild, Esq. Attorney-at-Law P. O. Box 12097 Charleston, South Carolina 29412

Mr. Jesse L. Riley Carolina Environmental Study Group 854 Henley Place Charlotte, North Carolina 28207

OFFICIAL COPY

