

P.O. Box 101, New Hill, N.C. 27562 July 25, 1984

Mr. James P. O'Reilly United States Nuclear Regulatory Commission Region II 101 Marietta Street, Northwest (Suite 2900) Atlanta, Georgia 30323

NRC-247

CAROLINA POWER & LIGHT COMPANY SHEARON HARRIS NUCLEAR POWER PLANT 1986 - 900,000 KW - UNIT 1 RAB EMERGENCY AIR CLEANING UNITS -WELD DEFICIENCIES, ITEM 180

Dear Mr. O'Reilly:

On June 28, 1984, Mr. N. J. Chiangi notified the NRC (Mr. A. Hardin) of a potentially reportable item per the provisions of 10CFR50.55(e) and 10CFR, Part 21. The NRC was informed that weld deficiencies were identified in four RAB Emergency Air Cleaning Units supplied by CTI Nuclear, Inc.

CP&L is currently awaiting Ebasco to complete an analysis of the welded connections which were identified as deficient. It is projected that the analysis will be received and a report on the report bility of this item will be issued by August 30, 1984.

Than! you for your consideration in this matter.

Yours very truly,

R. M. Parsons

Project General Manager

Shearon Harris Nuclear Power Plant

RMP/jam

Attachment

cc: Messrs. G. Maxwell/R. Prevatte (NRC-SHNPP) Mr. R. C. DeYoung (NRC)

