

APPENDIX B

NOTICE OF DEVIATION

Consolidated Edison Company
Indian Point Nuclear Generating Station, Unit 2

Docket No. 50-247
License No. DPR-26

As a result of the inspection conducted on June 18-22, 1984, and in accordance with the revised NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 8, 1984, the following deviation was identified:

IE Bulletin No. 79-19 states that licensees should "provide training and periodic retraining in the DOT and NRC regulatory requirements, the waste burial license requirements and in your (the licensee's) instructions and operating procedures for all personnel involved in the transfer, packaging and transport of radioactive material..." In your response to IE Bulletin No. 79-19, dated September 24, 1979, you stated that "training and periodic retraining in the DOT and NRC regulatory requirements, the waste burial license requirements, and instructions and operating procedures for all personnel involved in the transfer, packaging and transport of radioactive material will be implemented by March 1, 1980. A record of training dates, attendees and subject material will be maintained."

Contrary to the above, Quality Control inspectors involved in the transport of radioactive materials have not been trained in DOT and NRC regulatory requirements, the waste burial license requirements and instructions and operating procedures.

Consolidated Edison Company is hereby requested to submit to this office within 30 days of the date of the letter which transmitted this Notice, a written statement of explanation in reply, including for each deviation: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further deviations; and (3) the date when corrective action will be completed.

8408200530 840801
PDR ADOCK 05000247
G PDR

OFFICIAL RECORD COPY

DL50-247/84-14 - 0006.0.0
07/20/84