The Light company

COMPANY
Houston Lighting & Power South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483

April 13,1992 ST-HL-AE-4056 File No.: T07.03 10CFR50

U. S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555

South Texas Project Electric Generating Station Unit 2

Docket No. STN 50-499
Unit 2 Second Refueling Outage Inservice
Inspection Summary Report for Repairs and Replacements Addendum-1

In accordance with our letter ST-HL-AE-4035, dated March 16, 1992, enclosed is the Unit 2 second refueling outage (2RE02) Inservice Inspection Summary Report for Repairs and Replacements (Addendum -1) performed under the ASME Code, Section XI at the South Texas Project Electric Generating Station. This Summary Report includes the period from completion of the first refueling outage (December 11, 1990) to completion of the second refueling outage (December 18, 1991).

If you should have any questions on this matter, please contact Mr. A. W. Harrison at (512) 972-7298.

William J. Jump

Manager,

Nuclear Licensing

SDP/amp

Attachments: Per Attached Index

0.1114

AUTT

ST-HL-AE-4056 File No.: T07.03 Page 2

cc:

Regional Administrator, Region IV Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011

George Dick, Project Manager U.S. Nuclear Regulatory Commission Washington, DC 20555

J. I. Tapia
Senior Resident Inspector
c/o U. S. Nuclear Regulatory
Commission
P. O. Box 910
Bay City, TX 77414

J. R. Newman, Esquire Newman & Holtzinger, P.C. 1615 L Street, N.W. Washington, DC 20036

D. E. Ward/T. M. Puckett Central Power and Light Company P. O. Box 2121 Corpus Christi, TX 78403

J. C. Lanier/M. B. Lee City of Austin Electric Utility Department P.O. Box 1088 Austin, TX 78767

K. J. Fiedler/M. T. Hardt City ablic Service Board P. O. Box 1771 San Antonio, TX 78296 Rufus S. Scott Associate General Counsel Houston Lighting & Power Company P. O. Box 61867 Houston, TX 77208

INPO Records Center 1100 Circle 75 Parkway Atlanta, GA 30339~3064

Dr. Joseph M. Hendrie 50 Bellport Lane Bellport, NY 11713

D. K. Lacker
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

INDEX OF ATTACHMENTS

- 1. Cover Sheet
- 2. 2RE02 Inservice Inspection Summary Report for Repairs and Replacements, Addendum-x.