

ENCLOSURE 1

NOTICE OF VIOLATION

Wolf Creek Nuclear Operating Corporation
Wolf Creek Generating Station

Docket: 50-482
License: NPF-42

During an NRC inspection conducted on October 8 through November 18, 1995, one violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," (60 FR 34381; June 30, 1995), the violation is listed below:

Technical Specification 6.11 states, in part, that procedures for personal radiation protection shall be prepared consistent with the requirements of 10 CFR Part 20, and shall be approved, maintained, and adhered to for all operations involving personnel radiation exposure.

- (1) Procedure RPP 02-105, "RWP [Radiation Work Permit]," Revision 7, Step 9.2.5, requires the radiation work permit preparer to specify the radiological conditions for the immediate work area on the radiation work permit.

Contrary to the above, on November 13, 1995, a health physics technician sampled resin using Radiation Work Permit 950019, Revision 23, without radiological conditions for the immediate work area near the sample valve being specified on the radiation work permit.

- (2) Procedure RPP 02-105, "RWP [Radiation Work Permit]," Revision 7, Step 9.5.6, requires that health physics coverage requirements be specified on the radiation work permit for a system breach of contaminated systems.

Contrary to the above, on November 13, 1995, a health physics technician breached the contaminated resin transfer system to obtain a resin sample without health physics coverage requirements for the system breach and sampling operation being specified on the radiation work permit.

This is a Severity Level IV violation. (Supplement IV) (482/9424-01)

Pursuant to the provisions of 10 CFR 2.201, Wolf Creek Nuclear Operating Corporation is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the

corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Because the response will be placed in the NRC Public Document Room (PDR), to the extent possible, it should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction. However, if it is necessary to include such information, it should clearly indicate the specific information that should not be placed in the PDR, and provide the legal basis to support the request for withholding the information from the public.

Dated at Arlington, Texas,
this 4th day of December 1995