




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

August 8, 1984

W3P84-2207
Q-3-A1.01.04
Q-3-P43.T3

Mr. John T. Collins
Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Special Safety Inspection on Fire Protection
Notice of Deviation Items No. 382/8420-20 and
No. 382/8420-18

As requested by the subject notice, a summary of actions taken to correct the following deviations are submitted for your review:

Item No. 382/8420-20: "...procedure MM-7-010, Rev. 1, dated 5/1/83 failed to list a check for the required 6-year maintenance and 12-year hydrostatic test on dry chemical, stored pressure type of portable fire extinguishers with mild steel shells."

Response: A check for the required 6-year maintenance and 12-year hydrostatic test for dry chemical extinguishers has been listed in Revision 2 to procedure MM-7-010 which was approved by our Plant Operations Review Committee on July 26, 1984. This revision is expected to prevent the possibility of missing the required maintenance on dry chemical extinguishers. Full compliance with requirements will be accomplished on August 10, 1984, when the new procedure is fully implemented by plant manager approval.

Item No. 382/8420-18: "...procedure FP-1-004, Rev. 2, fails to provide an adequate surveillance procedure to ensure that the minimum inventory of personnel protective equipment is verified."


8408230284 840817
PDR ADOCK 05000382
PDR
Q

Mr. John T. Collins
W3P84-2207
August 8, 1984
Page 2.

Response: FP-1-004 was deleted and the applicable surveillance requirement was included in procedure FP-1-019, "Fire Brigade Equipment." No further actions are necessary in that the equipment necessary for fire brigade operations has been adequately provided along with the necessary administrative procedures. As of June 6, 1984, Waterford 3 has been in full compliance with the requirement to ensure verification of a minimum inventory of personnel protective equipment.

It is expected the corrective actions described are sufficient to resolve the subject deviations. Should you have any further questions or desire additional information please contact our fire protection licensing engineer Kevin Curley at (504) 363-8950.

Yours very truly,



K. W. Cook
Nuclear Support and Licensing Manager

KWC/KNC/smb

cc: E. L. Blake, W. M. Stevenson, J. E. Gagliardo, D. M. Crutchfield,
J. Wilson, G. L. Constable, D. J. Kubicki, N. Fiorvante

NS40476SEG