

Entergy Operations, Inc. River Bend Station 5485 U.S. Highway 61 P.O. Box 220 St. Francisville, LA 70775 Tel 504 336 6225 Fax 504 635 5068

James J. Fisicaro Director Nuclear Safety

December 12, 1995

U.S. Nuclear Regulatory Commission Document Control Desk Mail Stop P1-37 Washington, D.C. 20555

Subject:

River Bend Station - Unit 1

Docket No. 50-458

Final Special Report - Failure of Division I Starting Air Block and Vent Valve

File No.:

G9.5, G9.25.1.7


RBG-42241 RBF1-95-0294

Gentlemen:

On September 12, 1995, River Bend Station (RBS) submitted an Interim Special Report concerning a monthly operability surveillance, performed on the Division I Emergency Diesel Generator (EDG) on August 16, 1995. The EDG failed to start during the test. The Interim Special Report provided the event details as well as the initial results of River Bend's evaluations and statistical data. This find report documents the conclusions of the root cause investigation and corrective actions.

An independent offsite consultant performed a formal root cause evaluation to verify the preliminary conclusion and to establish the root causes of the failure. This investigation concluded that the root cause of the air block and vent valve failure is machining errors caused by the manufacturer that resulted in binding between the piston and bore. The investigation also concluded that this was an isolated failure; therefore, the corrective actions to replace the valve as documented in the previous report, are adequate to prevent recurrence. However, additional measures are being taken to enhance the valve inspection processes prior to installation. These actions will be tracked in accordance with the RBS corrective action program.

180016



Final Special Report - Failure of Division I Starting Air Block and Vent Valve December 12, 1995 RBG-42241 RBF1-95-0294 Page 2 of 2

If there are any questions concerning this issue please contact D. N. Lorfing at (504) 381-4157

Sincerely,

CC:

U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011

NRC Sr. Resident Inspector P.O. Box 1051 St. Francisville, LA 70775

INPO Records Center 700 Galleria Parkway Atlanta, GA 30339-3064

Mr. C.R. Oberg Public Utility Commission of Texas 7800 Shoal Creek Blvd., Suite 400 North Austin, TX 78757

Louisiana Department of Environmental Quality Radiation Protection Division P O. Box 82135 Baton Rouge, LA 70884-2135 ATTN: Administrator