

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.  
VICE PRESIDENT  
NUCLEAR OPERATIONS

July 24, 1984

JUL 30 A10:12

Mr. J. P. O'Reilly,  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II, Suite 2900  
101 Marietta Street, N.W.  
Atlanta, GA 30303


Subject: Virgil C. Summer Nuclear Station  
Docket No. 50/395  
Operating License No. NFF-12  
Notice of Deviation

Dear Mr. O'Reilly:

Please find attached South Carolina Electric and Gas Company's response to the Notice of Deviation as described in NRC Inspection Report No. 50-395/84-12 dated June 29, 1984.

Should you have any questions, please call at your convenience.

Very truly yours,



O. W. Dixon, Jr.

RJB:OWD/dwf/gj

cc: V. C. Summer	C. L. Ligon (NSRC)
T. C. Nichols, Jr./O. W. Dixon, Jr.	K. E. Nodland
E. H. Crews, Jr.	R. A. Stough
E. C. Roberts	G. Percival
W. A. Williams, Jr.	C. W. Hehl
D. A. Nauman	J. B. Knotts, Jr.
Group Managers	I & E Washington
O. S. Bradham	Site Licensing
C. A. Price	NPCF
D. A. Lavigne	File

Mr. J. F. O'Reilly  
Notice of Deviation  
July 24, 1984  
Page #2

NOTICE OF DEVIATION  
NRC INSPECTION REPORT 84-12

NRC Inspection Report No. 50-395/84-12 addresses NRC inspection activities for the Virgil C. Summer Nuclear Station May 1-31, 1984. Item 84-12-02 of the report identifies a deviation from a commitment to the Nuclear Regulatory Commission.

Deviation Description:

Final Safety Analysis Report (FSAR) Section 12.1.4.2 states that the Area Radiation Monitors are calibrated on a routine basis. This constitutes a commitment to the NRC regarding routine calibration of the Area Radiation Monitors.

Contrary to this commitment, as of May 24, 1984, the Area Radiation Monitors had not been included in the Licensee's Preventive Maintenance Program for routine calibration; and as a consequence, the following Area Radiation Monitor calibrations had expired:

<u>MONITOR</u>	<u>AREA SERVED</u>
RMG-2	Radiochemistry Lab Area
RMG-3	Sampling Room Area
RMG-12	Auxiliary Building Waste Holdup Tank Area

Corrective Action Taken:

Area Radiation Monitors RMG-2, 3, and 12 have been included in the Licensee's Preventive Maintenance Program, and calibration of the units was completed June 15, 1984.

Action Taken to Preclude Further Deviations:

The Licensee has verified that all Area Radiation Monitors, as identified in the FSAR, Table 12.1-19, are included in the Licensee's Preventive Maintenance Program.

The Licensee is also verifying calibration of all Area Radiation Monitors as identified in the subject FSAR Table. Any monitor identified as requiring calibration will be calibrated prior to startup following the present shutdown.