

DUKE POWER COMPANY

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER

VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

84 AUG 17, 1984 06
August 13, 1984

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 2900
Atlanta, Georgia 30323


Re: McGuire Nuclear Station
Docket Nos. 50-369, 50-370
IE Bulletin 84-02

Dear Mr. O'Reilly:

This letter is a supplemental response to IE Bulletin 84-02 which concerns failures of GE Type HFA relays in use in class 1E Safety Systems. Per Action Item 3, it has been determined that GE Type HFA relays, as described in the bulletin, are not used in any safety related systems at McGuire, therefore no further action is required.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge.

Very truly yours,



Hal B. Tucker

WHM:glb

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

8408280234 840813
PDR ADOCK 05000369
Q PDR

IE11 110