

01 JUN 5 12:31

June 1, 1984
L-84-147

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Units 1 and 2
Docket Nos. 50-335, 50-389
IE Bulletin 83-07

Our letter L-84-78 (dated April 4, 1984) stated that we would provide the Status of our Architect Engineer (A/E) and NSSS vendor review of Ray Miller, Inc. supplied materials for the St. Lucie Units 1 and 2. Below, please find the results of those reviews.

Our A/E (Ebasco Services) has reviewed their in-house records and determined that there are no direct Contracts between them as Agent for Florida Power & Light and Ray Miller, Inc. Through contact with the vendors on the project who supplied safety-related material our A/E has concluded that to the best of their knowledge, no sub-contracts were issued to the Ray Miller Company.

C-E has taken several steps to ensure that its customers are unaffected. The results of those investigations follow:

1. C-E Power Systems Group (PSG) reviewed its Approved Vendors List and ascertained that Ray Miller was not one of PSG's qualified nuclear suppliers.
2. C-E PSG has contacted all C-E manufacturing units and determined that no Ray Miller components were used in C-E manufactured equipment shipped to St. Lucie plants.
3. C-E PSG polled its nuclear equipment vendors to ascertain if any of its vendors had used Ray Miller as a subvendor. Of the more than 500 nuclear vendors, roughly 360 responded. Two positive responses were received. Neither response listed any FPL equipment.

C-E has made considerable effort to obtain a response from the delinquent vendors with little or no success. There are several possible reasons for the lack of response, among them are:

8408280236 840601
PDR ADCK 05000335
Q PDR

IE 11 '10
PEOPLE...SERVING PEOPLE


Mr. James P. O'Reilly
June 1, 1984
Page 2

1. Vendors are no longer in business.
2. Vendors do not want to expend the effort.

It is C-E's opinion that the results of this investigation indicate little chance of any Ray Miller products being installed at St. Lucie plants.

This completes our action on this bulletin. If there are any questions on this information, please call us.

Very truly yours,


J. W. Williams, Jr.
Group Vice President
Nuclear Energy

JWW/SAV/js

cc: Document Control Desk, USNRC
Harold F. Reis, Esquire
PNS-LI-84-198