



Entergy Operations, Inc.
1448 S.R. 333
Russellville, AR 72801
Tel 501 858-5000

December 15, 1995

2CAN129505

U. S. Nuclear Regulatory Commission
Document Control Desk
Mail Station P1-137
Washington, DC 20555

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Response To Notice Of Violation 50-368/9508-01

Reference: 2CAN119501 Dated November 2, 1995

Gentlemen:

Pursuant to the provisions of 10CFR2.201, the following is the subject response to the Notice of Violation identified during the inspection of activities associated with the Arkansas Nuclear One (ANO) Unit 2 Main Steam Safety Valve (MSSV) setpoints.

Entergy Operations agrees with this violation. The reason for the violation, corrective steps taken and corrective action to avoid further violations are documented in Licensee Event Report (LER) No. 50-368/95-005-00 dated November 2, 1995. Subsequent to identifying the unusually high setpoints of some of the MSSVs, corrective actions were implemented to properly test the MSSVs. Corrective actions have been implemented to prevent recurrence and are discussed in the LER. Full compliance with Unit 2 Technical Specifications was achieved prior to start-up following the recent refueling outage.

Should you have questions or comments, please call Mr. Dwight Mims at 501-858-4601

Very truly yours,

Dwight C. Mims
Director, Nuclear Safety

DCM/RMC

220021

9512220065 951215
PDR ADOCK 0500036B
PDR

LEO/
1/0

U. S. NRC
December 15, 1995
2CAN129505 Page 2

cc: • Mr. Leonard J. Callan
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

NRC Senior Resident Inspector
Arkansas Nuclear One
P.O. Box 310
London, AR 72847

Mr. George Kalman
NRR Project Manager Region IV/ANO-1 & 2
U. S. Nuclear Regulatory Commission
NRR Mail Stop 13-H-3
One White Flint North
11555 Rockville Pike
Rockville, MD 20852