

345



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

RELATED CORRESPONDENCE

DOCKET NUMBER 50-289 SP
PROD. SERVICE

August 27, 1984

DOCKETED
USNRC

'84 AGO 28 A10:16

Ellyn R. Weiss
General Counsel
Union of Concerned Scientists
Suite 1101
1346 Connecticut Avenue, N.W.
Washington, DC 20036

OFFICE OF SECRETARY
DOCKETING & SERVICE
BRANCH


Dear Ms. Weiss:

By letter dated July 19, 1984, you requested a list of the TMI-1 restart proceeding short-term actions that are not yet complete. The following short-term actions currently require some form of licensee action with subsequent NRC review and/or inspection:

- (1) emergency planning offsite communications test,
- (2) integrity of systems outside containment test program,
- (3) subcooling margin instrument error calibration procedure,
- (4) high pressure injection (HPI) system cross-connect valves and cavitating venturi testing, and
- (5) environmental qualification for radiation of components required to mitigate small-break loss of coolant accidents and loss of main feedwater events.

I trust this letter adequately responds to your request.

Sincerely,


Jack R. Goldberg
Counsel for NRC Staff

cc: TMI-1 Service List

8408280409 840827
PDR ADOCK 05000289
G PDR

DS07