


LOUISIANA

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

August 17, 1984

W3K84-1904
Q-3-A35.07.105

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



REFERENCE: LP&L letter W3K84-1657 dated July 19, 1984


Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 105
"Electrical Separation Deficiencies (Regulatory Guide 1.75)"
Third Interim Report

The above referenced letter indicated submittal of an Interim and/or Final Report to the USNRC on August 17, 1984.

At the present time, the additional walkdowns are completed, however, the rework generated by the engineering evaluations of the walkdown results is scheduled to be completed in late August 1984. An Interim and/or Final Report is scheduled to be submitted to the USNRC on August 31, 1984.

Very truly yours,


T. F. Gerrets

Corporate Quality Assurance Manager

TFG:CNH:VBR

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8408280436 840817
PDR ADDCK 05000382
S PDR

IE-2710

Mr. John T. Collins
August 16, 1984
W3K84-1904
Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814