

Carolina Power & Light Company

anterina attained

H. B. ROBINSON STEAM ELECTRIC PLANT POST OFFICE BOX 790 HARTSVILLE, SOUTH CAROLINA 29550 JUL 24 1984

Robinson File No: 13510E

Serial: RSEP/84-477

11:01A 08

Mr. James P. O'Reilly
Regional Administration
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, N. W.
Atlanta, Georgia 30323

H. B. ROBINSON SEG PLANT, UNIT NO. 2 DOCKET NO. 50-261 LICENSE NO. DPR-23 IE INSPECTION REPORT IER-84-11

Dear Mr. O'Reilly:

Thank you for your consideration of Carolina Power and Ligh⁺ Company's denial of the violation in the subject report. Carolina Power and Light has reviewed your June 29, 1984 staff evaluation of the denial and provides the requested information.

1. Corrective Steps Which Have Been Taken and Results Achieved.

In order to alleviate any concern the NRC may have on control of welding electrodes, Carolina Power and Light Company has made the following conservative changes to WP-502 in Revision 11.

- A. Coated electrodes returned to the issue station which were not issued in a portable rod caddie will be destroyed regardless of exposure time.
- B. Coated electrodes issued in a portable rod caddie shall be used or destroyed once they have been removed from the caddie.
- 2. Corrective Steps Which Will be Taken to Avoid Further Violation.

The corrective steps mentioned above should prevent recurrence.

3. Date When Full Compliance Will be Achieved.

Full compliance has been achieved.

8408290025 840807 PDR ADDCK 05000261 0 PDR Letter to Mr. James P. O'Reilly 'Serial: RSEP/84-477 Page 2

If you have any questions concerning this response, please contact my staff or me.

Very truly yours,

lling

R. E. Morgan General Manager H. B. Robinson SEG Plant

CLW/ml

+'