




**LOUISIANA**

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

August 10, 1984

W3K84-1879  
Q-3-A35.07.78

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



REFERENCE: LP&L Letter W3K84-1665 dated July 20, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-38?  
Significant Construction Deficiency No. 78  
"American Bridge Structural Steel Deficiencies"  
Eleventh Interim Report

The above referenced letter indicated submittal of an Interim/Final Report to the USNRC on August 10, 1984.

At the present time, review of corrective action is continuing and is scheduled to be completed in mid August 1984. The Final Report is scheduled to be submitted to the USNRC on August 31, 1984.

Very truly yours,

T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:VBR

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

*IE-27*  
*1/0*

8408290131 840810  
PDR ADOCK 05000382  
S PDR

Mr. John T. Collins

August 10, 1984

W3K84-1879

Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814