

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

August 10, 1984

W3K84-1880 Q-3-A35.07.108

AUG 2 0 1984

Mr. John T. Collins Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

REFERENCE: LP&L letter W3K84-1658 dated July 19, 1984


Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3

Docket No. 50-382

Significant Construction Deficiency No. 108 "Potential Failure to Comply With FSAR

Safe Shutdown Commitment" Third Interim Report



At the present time, corrective action is completed, however, verification of supporting documentation is scheduled to be completed in mid August 1984. The Final Report is scheduled to be submitted to the USNRC on August 31, 1984.

Very truly yours,

T. F. Gerrets

Corporate Quality Assurance Manager

TFG: CNH: VBR

cc: Director

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission

Washington, D.C. 20555

8408290139 840810 PDR ADOCK 05000382 IZ-01

TO: Mr. John T. Collins August 10, 1984 W3K84-1880 Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake Shaw, Pittman, Potts & Trowbridge 1800 M Street, N.W. Washington, D.C. 20036

Mr. W. M. Stevenson Monroe & Lemann 1424 Whitney Building New Orleans, Louisiana 70130

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. A. Cross 7910 Woodmont Avenue Suite 1200 Bethesda, Maryland 20814