




LOUISIANA

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

August 13, 1984

W3K84-1884
Q-3-A35.07.60

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



REFERENCE: LP&L letter W3K84-1656 dated July 19, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 60
"Turnover Documentation and Inadequate Hanger Weld Problems T&B"
Tenth Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on August 10, 1984

At the present time, walkdowns and minor rework are scheduled to be completed in late August 1984. The Final Report is scheduled to be submitted to the USNRC on August 31, 1984.

Very truly yours,

T. F. Gerrets
T. F. Gerrets

Corporate Quality Assurance Manager

TFG:CNH:VBR

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

B408290145 B40813
PDR ADOCK 05000382
S PDR

IE-27
1/0

Mr. John T. Collins

August 13, 1984

W3K84-1884

Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814