SAFEGUARDS INFORMATION



NUCLEAR REGULATORY COMMISSION

REGION II 101 MARIETTA STREET, N.W., SUITE 2900 ATLANTA, GEORGIA 30323

Report Nos.: 50-325/92-08 and 50-324/92-08

Licensee: Carolina Fower and Light Company

P. O. Box 1551 Raleigh, NC 27602

Docket Nos.: 50-325 and 50-324

License Nos.: DPR-71 and DPR-62

Facility Name: Brunswick 1 and 2

Inspection Conducted: March 23-27, 1992

Inspector: Wall Senior Safeguards

Stansberry Safeguards

Approved by:

D. R. McGuire, Chief Safeguards Section

Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards

SUMMARY

Scope:

This special, announced inspection was conducted in the area of the Physical Security Program for Power Reactors. Specifically, Management Support, Plan (and Procedures). Audit. Maintenance and Compensatory Measures were inspected. Additionally, the licensees corrective actions to a prior violation (91-17-01) were reviewed.

Results:

In the areas inspected, one non-cited violation was identified relative to the licensee maintaining and repairing vital area doors and their associated card readers, as well as improving search equipment and better defining the interior isolation zone of the protected area barrier. The licensee's response to this non-cited violation should improve the prioritization and scheduling of maintenance for security equipment. (NCV No. 92-08-01)

The licensee currently is on schedule to complete all the corrective actions for violation 91-17-01 which will meet, and in some instances exceed, NRC criteria.

SAFEGUARDS INFORMATION