



Carolina Power & Light Company

Brunswick Nuclear Project
P. O. Box 10429
Southport, NC 28461-0429
April 27, 1992

FILE: B09-13520

10CFR21

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNITS 1 AND 2
DOCKET NO. 50-325 AND 50-324
LICENSE NO. DPR-71 AND DPR-62
NOTIFICATION OF A 10CFR21 REPORTABLE OCCURRENCE

This confirms the telephone conversation at 1601 hours on April 24, 1992, between Mr. Scarfo (of your staff) and Mr. Godley (of my staff) which satisfied the requirements of 10CFR21 reporting criteria. It reported that, during initial Plant construction, defectively installed bolting of Emergency Diesel Generator Building internal wall seismic supports occurred.

Very truly yours,

J. W. Spencer, General Manager
Brunswick Nuclear Project

GMT/gmt

Enclosure

cc: Mr. S. D. Ebnetter
Mr. N. S. Le
Mr. R. L. Prevatte

9205010230 920427
PDR ADOCK 05000324
S PDR

TE19