LICENSE NO. 29-02477-09 DOCKET NO. 030-20952 CONTROL NO. 17767

United Stated Testing Co., Inc. ATTN: Carl B. Yoder, P.E. Radiation Safety Officer 1415 Park Avenue Hoboken, NJ 07030

Centlemen:

This letter is in response to your application, dated June 21, 1984, to amend license number 29-02477-09.

- 1. Please note that the Technical Operations Model 416 source exchanger is approved only for cobalt-60 sources. Accordingly you will need to submit the model number of the Technical Operations source exchanger that is approved by the NRC to use with the Tech-Ops Model 684 camera that will be holding the Tech-Ops Model A424-20 iridium-192 radiography source of 200 curies activity.
- 2. Please specify the model number of the Tech-Ops source exchanger you will use for the Tech-Ops Model 616 camera that will contain the Tech-Ops Model A58101-8 iridium-192 radiography source of 200 curies.

We will continue our review of your application upon receipt of this information. Please reply in duplicate and refer to Control No. 17767.

Sincerely,

Original Signed By: John E. Glenn

8408290402 840727 NMS LIC30 29-02477-09 PDR John E. Glenn, Ph.D., Chief Nuclear Materials Section B Division of Engineering and Technical Programs



MAVarela 07/30/84

OFFICIAL RECORD COPY

Mid

7-3-84

15	FROM:	Licensing Assistance Section Fuel Cycle Material Safety Office of Nuclear Material Safety Sa	afeguards
	Enclosed is the original copy of the application for a pending licensing action to be processed by your region.		
	CONTROL NO.	17767	
	LICENSEE: United States Desting Co. Dor LICENSE NUMBER: 29-02477 DOCKET NUMBER: 30-20952		
	LICENSE NUM	IBER: 29-02477	DOCKET NUMBER: 30-20952
	The duplicate copy of the application has already been sent to your region. Attached also is the official file. Please return the duplicate folder to LAS, FCMS, upon receipt of this file.		
	******	**********	*************
	FOR LFMB USE Fee Category and Amount: 30 #330		
	Correct fee	e has been paid.	
	Application	may be processed for: amendmen	nt renewal license
	LFMB Review	ver: 7. Brown	29 2/

Region I

License Fee Management Branch

NOTE FOR:

THRU: