

ENCLOSURE 1

NOTICE OF VIOLATION

Entergy Operations, Inc.
Waterford Steam Electric Station, Unit 3

Docket: 50-382
License: NPF-38

During an NRC inspection conducted on October 1 through November 11, 1995, two violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," (60 FR 34381; June 30, 1995), the violations are listed below:

- A. Technical Specification 6.8.1.a requires, in part, that written procedures be established, implemented, and maintained covering the activities recommended in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978. Regulatory Guide 1.33, Appendix A, "Quality Assurance Program Requirements," Section 9, requires that the licensee have maintenance procedures.

Procedure UNT-005-009, "Reporting and Evaluating Out-of-Calibration Measuring and Test Equipment," Section 4.7, stated, in part, that the user is responsible for timely reporting of suspect, damaged, lost, inoperative, or misplaced measuring and test equipment to the measuring and test equipment facility. Procedure UNT-005-011, "Calibration and Control of Measuring and Test Equipment," Section 4.4, states, in part, that users are responsible for the immediate return of suspect measuring and test equipment.

Contrary to the above, on October 13, 1995, personnel failed to implement a maintenance procedure in that maintenance technicians using suspect test equipment did not report or immediately return the suspect measuring and test equipment to the measuring and test equipment facility.

This is a Severity Level IV violation (Supplement I). (382/9509-01)

- B. 10 CFR 73.55(d)(7)(i)(B) requires, in part, that the licensee positively control all points of personnel access to vital areas.

Contrary to the above, on October 25, 1995, the licensee failed to provide positive control of personnel access to a vital area in that three individuals gained access to a vital area without their access authorization being verified by the licensee.

This is a Severity Level IV violation (Supplement III). (382/9509-02)

Pursuant to the provisions of 10 CFR 2.201, Entergy Operations, Inc. is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should

be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Because the response will be placed in the NRC Public Document Room (PDR), to the extent possible, it should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction. However, if it is necessary to include such information, it should clearly indicate the specific information that should not be placed in the PDR, and provide the legal basis to support the request for withholding the information from the public.

Dated at Arlington, Texas
this 22nd day of *December* 1995