

APR 24 1992

DOD (DCB)
RWD

Docket No. 50-282
Docket No. 50-306

Northern States Power Company
ATTN: Mr. L. R. Eliason
Vice President, Nuclear
Generation
414 Nicollet Mall
Minneapolis, MN 55401

Dear Mr. Eliason:

This refers to the routine safety inspection conducted by Mr. M. L. Dapas and others of this office from February 18 through April 13, 1992, of activities at the Prairie Island Nuclear Generating Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-42 and No. DPR-60, and to the discussion of our findings with Mr. M. D. Wadley and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a) of the Commission's regulations, a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosure: Inspection Reports
No. 50-282/92004(DRP);
No. 50-306/92004(DRP)

See Attached Distribution

yes RTII SJB Bywater 4/23	yes RTII RWD Jorgensen	yes RTII Ring para 6	yes RTII Creed para 8,9.b	yes RTII Gregor para 7,9.e	yes RTII RWD Shafer
---------------------------------------	---------------------------------	-------------------------------	------------------------------------	-------------------------------------	------------------------------

9205050024 920424
PDR ADDCK 05000282
Q PDR

IFD
111



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

APR 17 1992

Docket No. 50-282
Docket No. 50-306

Northern States Power Company
ATTN: Mr. L. R. Eliason
Vice President, Nuclear
Generation
414 Nicollet Mall
Minneapolis, MN 55401

Dear Mr. Eliason:

This refers to the routine safety inspection conducted by Mr. M. L. Dapas and others of this office from February 18 through April 13, 1992, of activities at the Prairie Island Nuclear Generating Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-42 and No. DPR-60, and to the discussion of our findings with Mr. M. D. Wadley and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a) of the Commission's regulations, a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

for *RW DeSoyette*
W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosure: Inspection Reports
No. 50-282/92004(DRP);
No. 50-306/92004(DRP)

See Attached Distribution

Distribution:

cc w/enclosure:

E. L. Watzl, Site Manager,
Prairie Island Site

M. Sellman, Plant Manager

DCD/DCB (RIDS)

OC/LFDCB

Resident Inspector, RIII

Resident Inspector, RIII Monticello

John W. Ferman, Ph.D.,

Nuclear Engineer, MPCA

State Liaison Officer, State
of Minnesota

Prairie Island, LPM, NRR

Robert M. Thompson, Administrator
Wisconsin Division of Emergency
Government