

APPENDIX A

NOTICE OF VIOLATION

Entergy Operations, Inc.
Arkansas Nuclear One, Unit 1

Docket: 50-313
License: DPR-51

During an NRC inspection conducted during the period March 1-28, 1992, a violation of requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

Technical Specification 6.8.1 requires, in part, that written procedures shall be established, implemented, and maintained covering surveillance and test activities of safety-related equipment.

Step 8.2.1 of Special Work Plan 1409.409, "Service Water System Loop II Hydrostatic Test (2nd 10 YR Cycle)," Revision 0, required that blanks be installed at the inlet/outlet flanges of Coolers VUC-1C and -1D.

Procedure 1092.189, "10 Year ISI Hydrostatic/Pneumatic Test Program Implementation," specified in Section 6.2.4.D that filling and venting of the system will be performed when all the system alterations have been completed.

Contrary to the above, on March 26, 1992, Loop II of the service water system was filled, vented, and pressurized to hydrostatic test pressure without installing the blanks at the inlet/outlet flanges of Coolers VUC-1C and -1D.

This is a Severity Level IV violation. (Supplement 1) (313-92007-01)

Although Section 2.201 requires you to submit to this office, within 20 days of your receipt of this Notice, a written statement of explanation, we note that the corrective actions being taken adequately address the concerns identified within the Notice of Violation. Therefore, no response with respect to this Notice is required.

Dated at Arlington, Texas,
this 4th day of May 1992