**NORTHEAST UTILITIES** 



THE CORRECTION CONTINUES FOWER COMPARY
WEBTERN MASSACHEBETTS SEECTHS COMPANY
HIS YORK WATER FOWER COMPANY
NORTHEAST UNLITTES SERVICE OMPANY
WIGHTHAS TO MASSACHE SERVICE TOWNS

General Offices . Selden Street, Berlin, Connecticut

P.O. BOX 270 HARTFORD, CONNECTICUT 06141-1270 (203) 685-5000

April 30, 1992

Docket No. 50-336 814126

Re: Inspection Report 50-336/91-16 RG 1.97

U.S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555

Gentlemen:

Millstone Nuclear Power Station, Unit No. 2 Inspection Report 50-336/91-16 Compliance to Regulatory Guide 1.97

The NRC Staff conducted an inspection of Millstone Unit No. 2's compliance with the guidance in Regulatory Guide (RG) 1.97, "Postaccident Instrumentation," on June 10-14, 1991. During the course of that inspection, certain questions were raised which required commitments by Northeast Nuclear Energy Company (NNECO) to provide certain information to the Staff on a schedule agreed to during the inspection.

One commitment called for the submittal of an update to the Millstone Unit No. 2 Final Safety Analysis Report (FSAR) regarding RG 1.97 instrumentation. In a letter dated June 14, 1991, NNECO committed to provide this information by April 1992. However, the development of a full and comprehensive FSAR update, including the RG 1.97 instrumentation list, will require additional time.

NNECO intends to meet a schedule of June 30, 1992, for submittal of Millstone Unit No. 2's FSAR update.

We regret any inconvenience this change in schedule may cause. Please contact us if you have questions.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

J. E. Opeka

Executive Vice President

cc: T. T. Martin, Region I Administrator

G. S. Vissing, NRC Project Manager, Millstone Unit No. 2

W. J. Raymond, Senior Resident Inspector, Millstone Unit Nos. 1, 2, and 3

(1) E. J. Mroczka letter to U.S Nuclear Regulatory Commission, "Inspection Report 50-336/91-16--Compliance to Regulatory Guide 1.97," dated June 14, 1991.

OS3422 REV 4-88

92056/0293 920430 PDR ADDCK 03000336 A03/0