



SAFEGUARDS INFORMATION  
UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30323

Report Nos.: 50-369/92-12 and 50-370/92-12

Licensee: Duke Power Company  
422 South Church Street  
Charlotte, NC 28242

Docket Nos.: 50-369 and 50-370 License Nos.: NPF-9 and NPF-17

Facility Name: McGuire 1 and 2

Inspection Conducted: April 6-10, 1992

Inspector: *D. Thompson* 5/5/92  
D. Thompson, Safeguards Inspector Date Signed

Accompanying Personnel: A. Tillman, Safeguards Inspector

Approved by: *D. R. McGuire* 5/5/92  
D. R. McGuire, Chief Date Signed  
Safeguards Section  
Nuclear Materials Safety and Safeguards Branch  
Division of Radiation Safety and Safeguards

SUMMARY

Scope:

This routine, unannounced inspection was conducted in the areas of Management Support; Security Program Plans; Security Audits; Protected Area and Vital Area Barriers; Detection and Assessment Aids; Alarm Stations; Communications; Power Supply; and Compensatory Measures.

Results:

In the areas inspected, one violation was identified.

It was noted that in the past year, six access control related events had occurred, the most serious on March 19, 1992, when an individual was issued the wrong access badge and prior to being granted entry was checked by two security officers, and the error was not detected. Additionally, two 1987 Regulatory Effectiveness Review (RER) deficiency items, which the licensee agreed needed to be resolved continued to exist. There were also two events of sleeping officers in the past year.

SAFEGUARDS INFORMATION

9205120084 920507  
PDR ADDCK 05000369  
G PDR

Copyright © 1992 by the  
Nuclear Regulatory Commission  
All rights reserved. No part of  
this document may be reproduced  
without the express written  
permission of the Commission.