



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

JAN 5 1996

TU Electric
ATTN: C. L. Terry, Group Vice President
Nuclear Production
Energy Plaza
1601 Bryan Street, 12th Floor
Dallas, Texas 75201-3411

SUBJECT: NRC INSPECTION REPORT 50-445/95-24; 50-446/95-24

This refers to the inspection conducted by Ms. Gail M. Good and other members of an NRC team during the period December 5-8, 1995, at the Comanche Peak Steam Electric Station, Units 1 and 2, facility. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed report.

Areas examined during the inspection included the implementation of your emergency plan and procedures during your emergency preparedness exercise. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The results of this inspection are documented in the enclosed report.


Two exercise weaknesses identified during the inspection are discussed in Sections 4 and 5 of the enclosed inspection report. The weaknesses involved the failure of the operations support center to implement repair priorities established by the technical support center and the failure to make a timely protective action recommendation.

Exercise weaknesses, according to 10 CFR Part 50, Appendix E.IV.F.2.g, are inspection findings that need to be corrected by the licensee. You are requested to provide this office with a description of your corrective measures and your schedule for completing these actions within 30 days after receipt of this letter. The NRC has concluded that information regarding the corrective actions taken to correct the exercise weakness involving the failure to make a timely protective action recommendation is already adequately addressed in the enclosed report. Therefore, you are not required to respond to this exercise weakness unless the description, therein, does not accurately reflect your corrective actions.

9601160395 960105
PDR ADOCK 05000445
G PDR

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room. Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,


Thomas P. Gwynn, Director
Division of Reactor Safety

Dockets: 50-445
50-446
Licenses: NPF-87
NPF-89

Enclosure:
NRC Inspection Report
50-445/95-24; 50-446/95-24
w/attachments

cc w/enclosure:
TU Electric
ATTN: Roger D. Walker, Manager of
Regulatory Affairs for Nuclear
Engineering Organization
Energy Plaza
1601 Bryan Street, 12th Floor
Dallas, Texas 75201-3411

Juanita Ellis
President - CASE
1426 South Polk Street
Dallas, Texas 75224

TU Electric
Bethesda Licensing
3 Metro Center, Suite 610
Bethesda, Maryland 20814

Morgan, Lewis & Bockius
ATTN: George L. Edgar, Esq.
1800 M. Street, NW
Washington, D.C. 20036

Texas Department of Licensing & Regulation
ATTN: G. R. Bynog, Program Manager/
Chief Inspector
Boiler Division
P.O. Box 12157, Capitol Station
Austin, Texas 78711

Honorable Dale McPherson
County Judge
P.O. Box 851
Glen Rose, Texas 76043

Texas Radiation Control Program Director
1100 West 49th Street
Austin, Texas 78756

Office of the Governor
ATTN: Susan Riefí, Director
Environmental Policy
P.O. Box 12428
Austin, Texas 78711

Chief, Technological Hazards Branch
FEMA Region 6
Federal Regional Center
800 North Loop 288
Denton, Texas 76201-3698

TU Electric

-4-

E-Mail report to D. Nelson (DJN)
E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IE35)

bcc distrib. by RIV:

L. J. Callan
Branch Chief (DRP/B)
MIS System
RIV File
Branch Chief (DRP/TSS)
C. A. Hackney, RSLO

Resident Inspector (2)
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)
DRS-PSB
Project Engineer (DRP/B)
T. Essig (NRR/PERB)
R. Hendrix, FEMA VI

DOCUMENT NAME: O:\CP524RP.GMG

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

SEPA: PSB	E		E		E		E		E
GMGood:cg	B	HFreeman	B	EFox	B	AMcQueen	B	BMurray	B
12/27/95		12/27/95		12/27/95		12/27/95		12/27/95	
D:DRS	W	PBB:DRP		D:DRS	N				
TPGwynn	W	BJohnson		TPGwynn	W				
12/27/95		12/4/95		12/5/95					

OFFICIAL RECORD COPY

E-Mail report to D. Nelson (DJN)
E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IE35)

bcc distrib. by RIV:

L. J. Callan
Branch Chief (DRP/B)
MIS System
RIV File
Branch Chief (DRP/TSS)
C. A. Hackney, RSLO

Resident Inspector (2)
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)
DRS-PSB
Project Engineer (DRP/B)
T. Essig (NRR/PERB)
R. Hendrix, FEMA VI

DOCUMENT NAME: O:\CP524RP.GMG

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

SEPA:PSB	E		E		E		E		E
GMGood:cg	B	HFreeman	B	EFox	B	AMcQueen	B	BMurray	B
12/27/95		12/27/95		12/27/95		12/27/95		12/27/95	
D:DRS	N	PBB:DRP		D:DRS	N				
TPGwynn	N	BJohnson		TPGwynn	N				
12/1/95		12/4/95		12/5/95					

OFFICIAL RECORD COPY

140079